



INVESTIGATION REPORT  
BUILDING AND SAFETY/LAND DEVELOPMENT DIVISION

Location of Problem

2624 Florence

Locality

Description of problem:

- |  |  |
|--|--|
| <input type="checkbox"/> VACANT LOT                        | <input type="checkbox"/> VACANT HOUSE          |
| <input type="checkbox"/> TRASH, JUNK, DEBRIS IN YARD AREAS | <input type="checkbox"/> OVERGROWN VEGETATION  |
| <input type="checkbox"/> DISCARDED FURNITURE- APPLIANCES   | <input type="checkbox"/> INOPERABLE VEHICLE(S) |

Broken Windows, Plumbing is  
Bad, Back door is falling.

Requested by:

Ruben Gonzalez-

Request call back after investigation? Yes ☐ No ☐

Received by:

Helen McGregor

Date:

1/4/00

Assigned/Referred to:

Date:

Report of Investigation:

Investigator:

Title:

Date:

Copy Sent to:

Title:

Date:

Report Phoned to:

Title:

Date:

DISKAM/AM20.12A/07/95

JOB  
ADDRESS 2624 E. FLORENCE  
OWNER JM KEITH 3019 Florence  
A COMMERCIAL BUSINESS CL 90256

## NOTICE OF VIOLATION

The work performed is in violation of the Ordinance(s)  
indicated below:

☒ Building Code ☒ Plumbing Code  
☐ Mechanical Code ☒ Electrical Code  
☐ Grading Code ☐ Zoning Code

ALL ELECTRICAL AND PLUMBING  
REPAIRS MUST BE DONE BY A STATE  
LICENSE CONTRACTOR  
DESCRIPTION: REAR WINDOW

BROKEN, TRAP UNDER  
SINK BROKEN AND LEAKING.  
HOLES IN BATHROOM WALLS.  
ELECTRICAL PANEL ON REAR  
WALL NEEDS REPAIR AND  
SECURED TO WALL.  
EXPOSED ELECTRICAL WIRING  
IN BATHROOM CEILING.

### STOP ALL WORK

☐ Submit plans for the cited work within 10 days  
to the office listed above and apply for a plan  
check for the required permit(s).

☒ Obtain permit(s) within 10 days at the office  
listed above for the cited work.

☐ A referral has been made to the Enforcement  
Section of the Department of Regional  
Planning.

1-5-2000

DATE

H. Polgar  
INSPECTOR'S SIGNATURE